


PROFORMA FOR THE SAFETY OF SCHOOL BUILDING PART- 1

(To be filled by the Head of School/ Institute)

1. Name of the School Jalandhar Public School
2. Location Kamal Vihar ,Near Surya Enclave,Jalandhar
18653SFT
3. Plot Area 14603SFT
4. Plinth Area 3(THREE)
5. Number of Storey's 2008-09
6. Year of Construction of Building Mr. Raman Kumar Khosla
7. If the building has been constructed under the supervision
55-Puda Complex Ladowali, Jalandhar
- a) Name Of The Engineer With Qualification
- b) Address of Engineer
- c) Set of Structural drawings used in the construction, if available
- d) Name & address of Architect with qualification
8. Whether the building has been constructed for the purpose
 YES/ NO
- a) School YES/ NO
- b) Residential Purpose and converted for use as a School
9. Materials used for roofs
 YES/ NO
- a) R.C.C. Slabs/R.B.C. Slabs YES/ NO
- b) R.S. Joist & Battons YES/ NO
- c) Wooden joists & Battons
10. Materials used for walls
YES/ NO
- a) Mud Mortar YES/ NO
- b) Cement Mortar YES/ NO
- c) Lime Mortar
11. Flooring
 YES/ NO
- a) Conglomerate YES/ NO
- b) Terrazo YES/ NO
- c) Brick Paving.
12. A detailed drawing indicating dimensions of the rooms
Alongwith size and location of doors and windows
(Attached)


Principal
Jalandhar Public School
Kamal Vihar, Jalandhar


Principal
Jalandhar Public School
Kamal Vihar, Jalandhar

Signature with Stamp of the seal Of
the School/Institution.

PART-II


(To be filled by the S.D.E.)
Jalandhar Public School, Kamal Vihar Jalandhar


- a) I have visited the above mentioned school on dated01.4.2021.....And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used) upto 31.3.2022 (2021-2022). The school building is VISIBLY SAFE & can be used upto 31.3, 2022 (2021-2022).


Sub Divisional Engineer,

No: - 842

Dt: - 1/4/2021


Sub Divisional Engineer
Province Sub Divn No. 1,
PWD B&R Br, Jalandhar Cantt


Principal
Jalandhar Public School
Kamal Vihar, Jalandhar


Chairman
Jalandhar Public School
Kamal Vihar, Jalandhar